EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	("5156053").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/23 09:12
L2	6	(("5505095") or ("5549007") or ("5585570")).PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/23 09:13
L3	182968	((position proximity angle) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:00
L4	3194	3 and bend\$5.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 09:36
.L5	1516	4 and (turn\$5 arcute pivot rotat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:04
L6	590	5 and control.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 09:41
L7	8	6 and chuck.clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 09:42
L8	0	6 and ((crack\$5) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 09:54
L9	18	6 and ((crack\$5 fail\$6 break\$5 tear\$5 torn cut\$5) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:03
L10	2085	((bending) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:00

EAST Search History

				,		
L11	588	3 and 10	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:03
L12	24	11 and ((crack\$5 fail\$6 break\$5 tear\$5 torn cut\$5) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:25
L13	13	12 and (turn\$5 arcute pivot rotat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:18
L14	255	11 and (turn\$5 arcute pivot rotat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:25
L15	232	11 and (pivot rotat\$4).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 10:25
L16	4	15 and ((crack\$5 fail\$6 break\$5 tear\$5 torn) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:19
L17	660	10 and (turn\$5 arcute pivot rotat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:28
L18	8	17 and ((crack\$5 fail\$6 break\$5 tear\$5 torn) near3 (measur\$5 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:24
L19	56	(73/851).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/23 11:27
L20	391	(73/849).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/03/23 11:27
L21	4	20 and 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/03/23 11:27

EAST Search History

L22	51	20 and (turn\$5 arcute pivot rotat\$4). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:38
L23	1	controlling near3 semiconducting near3 carbon near3 nanotube near3 material	US-PGPUB; USPAT; EPO; JPO	OR	ON	2006/03/23 11:39

3/23/06 1:03:51 PM C:\Documents and Settings\MNoori\My Documents\EAST\Workspaces\max.wsp Page 3